



DEPARTMENT OF  
WATER RESOURCES

# DELTA AREA *Fact Sheet* **Site 16.2**

**Critical Levee Erosion Site**

## Emergency Levee Repairs

### Location

River: Steamboat Slough

River Mile: 16.2

Latitude/Longitude:

38.191912/121.639231

Nearest Impact Area:

Rio Vista

County: Solano

Bank: Right

### Type of Damage

Bank erosion

### Length of Repair


330 feet (approximate)

### Repair Type

Rock slope protection

### Lead Agency

Department of Water Resources



**For further information,  
please contact:**

**Elizabeth Scott**  
**DWR Public Affairs Office**  
**(916) 835-5344**  
**[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)**

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

**[www.levees.water.ca.gov](http://www.levees.water.ca.gov)**